HOME REPORT







Energy Performance Certificate

Energy Performance Certificate (EPC)

Dwellings

Scotland

FLAT 1/1, 7 SPRINGBANK STREET, GLASGOW, G20 7EF

Dwelling type:Mid-floor flatDate of assessment:16 August 2016Date of certificate:16 August 2016

Total floor area: 68 m²

Primary Energy Indicator: 314 kWh/m²/year

Reference number: 5616-2228-7000-0406-9996 **Type of assessment:** RdSAP, existing dwelling

Approved Organisation: Elmhurst

Main heating and fuel: Boiler and radiators, mains


gas

You can use this document to:

- . Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£2,607	See your recommendations	
Over 3 years you could save*	£1,053	report for more information	

^{*} based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band D (61)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band D (56)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years	Available with Green Deal
1 Internal or external wall insulation	£4,000 - £14,000	£435.00	Ø
2 Low energy lighting	£10	£33.00	
3 Heating controls (room thermostat)	£350 - £450	£129.00	Ø

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.



The Green Deal may allow you to make your home warmer and cheaper to run at no up-front capital cost. See your recommendations report for more details.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Sandstone or limestone, as built, no insulation (assumed)	****	***
	Solid brick, as built, no insulation (assumed)	****	***
Roof	(another dwelling above)	_	_
Floor	(other premises below)	_	_
Windows	Single glazed	****	****
Main heating	Boiler and radiators, mains gas	****	★★★★☆
Main heating controls	Programmer, TRVs and bypass	★★★☆☆	★★★☆☆
Secondary heating	None	_	_
Hot water	From main system	****	★★★★ ☆
Lighting	Low energy lighting in 71% of fixed outlets	****	****

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 55 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 3.8 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 1.8 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£1,947 over 3 years	£1,059 over 3 years	
Hot water	£477 over 3 years	£348 over 3 years	You could
Lighting	£183 over 3 years	£147 over 3 years	save £1,053
Totals	£2,607	£1,554	over 3 years

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Recommended measures		Indicative cost	Typical saving	Rating after improvement		Green
Re	commended measures	indicative cost	per year	Energy	Environment	Deal
1	Internal or external wall insulation	£4,000 - £14,000	£145	D 67	D 64	
2	Low energy lighting for all fixed outlets	£10	£11	D 68	D 65	
3	Upgrade heating controls	£350 - £450	£43	C 69	D 67	
4	Replace boiler with new condensing boiler	£2,200 - £3,000	£93	C 73	C 73	
5	Replace single glazed windows with low-E double glazed windows	£3,300 - £6,500	£60	C 76	C 76	


Measures which have a green deal tick of are likely to be eligible for Green Deal finance plans based on indicative costs. Subsidy also may be available for some measures, such as solid wall insulation. Additional support may also be available for certain households in receipt of means tested benefits. Measures which have an orange tick may need additional finance. To find out how you could use Green Deal finance to improve your property, visit www.greenerscotland.org or contact the Home Energy Scotland hotline on 0808 808 2282.

Alternative measures

There are alternative improvement measures which you could also consider for your home. It would be advisable to seek further advice and illustration of the benefits and costs of such measures.

- Biomass boiler (Exempted Appliance if in Smoke Control Area)
- Air or ground source heat pump
- Micro CHP

Choosing the right improvement package





About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Internal or external wall insulation

Internal or external wall insulation involves adding a layer of insulation to either the inside or the outside surface of the external walls, which reduces heat loss and lowers fuel bills. As it is more expensive than cavity wall insulation it is only recommended for walls without a cavity, or where for technical reasons a cavity cannot be filled. Internal insulation, known as dry-lining, is where a layer of insulation is fixed to the inside surface of external walls; this type of insulation is best applied when rooms require redecorating. External solid wall insulation is the application of an insulant and a weather-protective finish to the outside of the wall. This may improve the look of the home, particularly where existing brickwork or rendering is poor, and will provide long-lasting weather protection. Further information can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk). It should be noted that planning permission might be required and that building regulations apply to this work so it is best to check with your local authority whether a building warrant or planning permission will be required.

2 Low energy lighting

Replacement of traditional light bulbs with energy saving recommended ones will reduce lighting costs over the lifetime of the bulb, and they last up to 12 times longer than ordinary light bulbs. Also consider selecting low energy light fittings when redecorating; contact the Lighting Association for your nearest stockist of Domestic Energy Efficient Lighting Scheme fittings.

3 Heating controls (room thermostat)

The heating system should have a room thermostat to enable the boiler to switch off when no heat is required. A competent heating engineer should be asked to do this work. Insist that the thermostat switches off the boiler as well as the pump and that the thermostatic radiator valve is removed from any radiator in the same room as the thermostat. Building regulations generally apply to this work and a building warrant may be required, so it is best to obtain advice from your local authority building standards department and from a qualified heating engineer.

4 Condensing boiler

A condensing boiler is capable of much higher efficiencies than other types of boiler, meaning it will burn less fuel to heat this property. This improvement is most appropriate when the existing central heating boiler needs repair or replacement, however there may be exceptional circumstances making this impractical. Condensing boilers need a drain for the condensate which limits their location; remember this when considering remodelling the room containing the existing boiler even if the latter is to be retained for the time being (for example a kitchen makeover). Building regulations generally apply to this work and a building warrant may be required, so it is best to obtain advice from your local authority building standards department and from a qualified heating engineer.

5 Double glazed windows

Double glazing is the term given to a system where two panes of glass are made up into a sealed unit. Replacing existing single-glazed windows with double-glazed windows will improve comfort in the home by reducing draughts and cold spots near windows. Double-glazed windows may also reduce noise, improve security and combat problems with condensation. Building regulations apply to this work and planning permission may also be required, so it is best to check with your local authority on what standards need to be met. A building warrant is not required if the windows comply with the current requirements.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

You could receive Renewable Heat Incentive (RHI) payments and help reduce carbon emissions by replacing your existing heating system with one that generates renewable heat and, where appropriate, having your loft insulated and cavity walls filled. The estimated energy required for space and water heating will form the basis of the payments. For more information go to www.energysavingtrust.org.uk/scotland/rhi.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	8,480	N/A	N/A	(2,347)
Water heating (kWh per year)	2,393			_

Addendum

This dwelling has stone walls and so requires further investigation to establish whether these walls are of cavity construction and to determine which type of wall insulation is best suited.

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Mr. Alan Bain Assessor membership number: EES/012303

Company name/trading name: Hardies Property & Construction Consultants

Address: Swilken House 35 Largo Road

St Andrews KY16 8NJ 0141 585 6373

Phone number: 0141 585 6373

Email address: alan.bain@hardies.co.uk

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Opportunity to benefit from a Green Deal on this property

Under a Green Deal, the cost of the improvements is repaid over time via a credit agreement. Repayments are made through a charge added to the electricity bill for the property.

To see which improvements are recommended for this property, please turn to page 3. You can choose which improvements you want to install and ask for a quote from an authorised Green Deal provider. They will organise installation by an authorised Green Deal installer. If you move home, the responsibility for paying the Green Deal charge under the credit agreement passes to the new electricity bill payer.

For householders in receipt of income-related benefits, additional help may be available.

To find out more, visit www.greenerscotland.org or call 0808 808 2282.

Authorised home energy assessment

Finance at no upfront cost

Choose from authorised installers May be paid from savings in energy bills

Repayments stay with the electricity bill payer





survey report on:

Property address	FLAT 1/1 7 SPRINGBANK STREET GLASGOW G20 7EF
Customer	MR GRANT DONNAN
Customer address	FLAT 1/1 7 SPRINGBANK STREET GLASGOW G20 7EF
Prepared by	Hardies Property & Construction Consultants
Date of inspection	16th August 2016



PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property¹.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.



The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in the expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

¹ Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions. The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:-

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report ² will be from information contained in the Report and the generic Mortgage Valuation Report.

² Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;

- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller:
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2. Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3. Category 1: No immediate action or repair is needed.

WARNING:

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value, the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	The subjects comprise a first floor flat contained in a four storey tenement building comprising eight separate dwelling flats with a funeral parlour and a vacant shop unit on the ground floor.
Accommodation	First Floor: Hall, Living Room, Kitchen, 2 Bedrooms, Bathroom.
Gross internal floor area (m²)	68 sq m.
Neighbourhood and location	The subjects are located within an established residential area within the Firhill district of Glasgow to the north west of the city centre. Surrounding properties comprise similar tenemental flats and modern houses. All local amenities are available within a short distance.
Age	115 years.
Weather	At the time of our inspection weather conditions were dry and sunny.
Chimney stacks	Visually inspected with the aid of binoculars where appropriate. A number of the chimneys have been removed and aluminium flues inserted. There is one remaining chimney which is of brick construction rendered externally.
Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate. Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally. Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property.


	If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so. No access obtained to the roof void. The roof hatch was padlocked at the time of our inspection and given the height of the hatch, being in excess of 3 metres from floor to ceiling, this hatch if open, would have been outwith the scope of inspection. The roof is presumed to be of traditional timber construction and externally there is a concrete tile finish. No clear sight was possible of the rear roof pitch from ground level. There would appear to be a section of flat roof over the bay window projection. No clear sight of this area was possible from ground level. This roof is presumed to be clad in lead or similar material.
Rainwater fittings	Visually inspected with the aid of binoculars where appropriate.
	The rainwater goods are of replacement alloy and PVC.
Main walls	Visually inspected with the aid of binoculars where appropriate.
	Foundations and concealed parts were not exposed or inspected.
	The main walls are of 600mm thick solid sandstone construction.
Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
	The windows to the property are single glazed timber type. The front entrance door is formed in timber as are the communal entrance doors.
External decorations	Visually inspected.
	Paint finishes to the windows and doors.
Conservatories / porches	Not applicable.
Communal areas	Circulation areas visually inspected.
	The common close has a concrete floor and the walls and ceilings are plastered and painted.

Garages and permanent outbuildings	None.
Outside areas and boundaries	Visually inspected.
	There is a communal back court to the rear of the property.
Calling	Viewelly, in an actual from the an lovel
Ceilings	Visually inspected from floor level.
	The ceilings to the property are predominantly of plasterboard.
Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	The internal walls are lined in plasterboard.
Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point.
	Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.
	Flooring is of suspended timber construction. Our inspection of flooring was restricted due to fitted floor coverings and furnishings.
Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were
	moved.
	Kitchen units were visually inspected excluding appliances.
	The kitchen has integrated timber wall and floor units. The internal joinery is formed in softwood timber.
Chimney breasts and fireplaces	None.
Chilling breasts and irreplaces	NOTE.
Internal decorations	Visually inspected.
	Paint finishes to walls and ceilings.
Cellars	None.

1	
Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on. Mains electrical supply. The electricity meter and distribution unit are located in the
	cupboard in the hall.
Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	Mains gas supply.
	The gas meter is located in the cupboard in the hall.
Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	Mains water supply.
	The plumbing installation appears to be of copper or PVC.
	The plumbing installation appears to be of copper or PVC. There is a three piece sanitary suite within the bathroom.
	There is a three piece sanitary suite within the bathroom.
Heating and hot water	
Heating and hot water	There is a three piece sanitary suite within the bathroom. Accessible parts of the system were visually inspected apart
Heating and hot water	There is a three piece sanitary suite within the bathroom. Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or
Heating and hot water	There is a three piece sanitary suite within the bathroom. Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or appliances. There is a gas fired boiler located in the kitchen, which serves the panel radiators throughout the property and also provides hot
Heating and hot water Drainage	There is a three piece sanitary suite within the bathroom. Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or appliances. There is a gas fired boiler located in the kitchen, which serves the panel radiators throughout the property and also provides hot water.
	There is a three piece sanitary suite within the bathroom. Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or appliances. There is a gas fired boiler located in the kitchen, which serves the panel radiators throughout the property and also provides hot water. The hot water tank is located in the cupboard in the hall.
	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or appliances. There is a gas fired boiler located in the kitchen, which serves the panel radiators throughout the property and also provides hot water. The hot water tank is located in the cupboard in the hall. Drainage covers etc. were not lifted.

Fire, smoke and burglar alarms	None.
Any additional limits to inspection	For flats / maisonettes
	Only the subject flat and internal communal areas giving access to the flat were inspected. If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation. The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general
	Condition and standard of maintenance. No access was obtained to the roof void. No clear sight was possible of the rear roof pitch from ground level.
	We have not carried out an inspection for Japanese Knotweed or other invasive plant species and unless otherwise stated for the purposes of this report we have assumed that there is no Japanese Knotweed or other invasive plant species within the boundaries of the property or in neighbouring properties. The identification of Japanese Knotweed or other invasive plant species should be made by a Specialist Contractor.

Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

- 1) Chimney pots
- (2) Coping stone
- 3) Chimney head
- 4) Flashing
- (5) Ridge ventilation
- 6) Ridge board
- 7) Slates / tiles
- (8) Valley guttering
- 9) Dormer projection
- 10 Dormer flashing
- 11) Dormer cheeks
- (12) Sarking
- (13) Roof felt
- (14) Trusses
- 15) Collar
- (16) Insulation
- 7) Parapet gutter
- 18) Eaves guttering
- 19) Rainwater downpipe
- 0) Verge boards /skews
- 21) Soffit boards
- 22) Partition wall
- 23) Lath / plaster
- (24) Chimney breast
- 25) Window pointing
- (6) Window sills
- (27) Rendering
- (28) Brickwork / pointing
- 29) Bay window projection
- (30) Lintels
- (31) Cavity walls / wall ties
- 32) Subfloor ventilator
- 33) Damp proof course
- 34) Base course
- 35) Foundations
- 36) Solum
- 37) Floor joists
- 38) Floorboards
- 9) Water tank
- 40) Hot water tank

2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	

Structural movement	
Repair category	1
Notes	There is evidence of settlement within the building, however this appears to be historic and not of an ongoing or progressive nature.

Dampness, rot and infestation	
Repair category	1
Notes	There was no significant evidence of dampness, rot or infestation noted to the property. It is understood that damp rot treatment works were carried out to the bathroom last year and all relevant guarantees for this work should be exhibited.

Chimney stacks	
Repair category	1
Notes	No significant defects were noted.

Roofing including roof space	
Repair category	1
Notes	The main roof of the property has been reclad in concrete tiles. This may have been carried out as part of a tenement refurbishment possibly carried out in the 1980's. This type of roof covering does, at best, have a limited life span of around 40 years and this can be affected either due to poor maintenance or adverse weather conditions. Further attention to roof coverings can be anticipated.

Rainwater fittings	
Repair category	2
Notes	Evidence of vegetation was noted to be growing in the guttering.

Main walls	
Repair category	2
Notes	Sections of stonework was showing signs of weathering. Vegetation was noted to be growing in sections of stonework to the rear.

Windows, external doors and joinery	
Repair category	2
Notes	Sections of the pointing at the windows was cracked.

External decorations	
Repair category	1
Notes	The external decoration was showing signs of weathering.

Conservatories/porches	
Repair category	-
Notes	None.

Communal areas	
Repair category	2
Notes	The common entrance hall and stairwell are weathered and the paintwork was flaking. It is understood from the vendor that there is a programme of redecoration scheduled to be undertaken to the common close and it should be confirmed that the flat's share of same has been paid.

Garages and permanent outbuildings	
Repair category	-
Notes	None.

Outside areas and boundaries		
Repair category	1	
Notes	No significant defects were noted.	
Ceilings	Ceilings	
Repair category	1	
Notes	No significant defects were noted.	
Internal walls		
Repair category	1	
Notes	No significant defects were noted.	
Floors including su	ıb-floors	
Repair category	1	
Notes	No significant defects were noted.	
Internal joinery and kitchen fittings		
Repair category	1	
Notes	No significant defects were noted.	
Chimney breasts and fireplaces		
Repair category	-	

Chimney breasts and fireplaces	
Repair category	-
Notes	None.

Internal decorations	
Repair category	1
Notes	The internal decoration is generally fresh.

Cellars	
Repair category	-
Notes	None.

Electricity	
Repair category	1
Notes	The electrical installation dates from the time of construction and is to a modern pattern.

Gas	
Repair category	1
Notes	The valuation below assumes that the gas installation to the property does comply with current Gas Safe standards.

Water, plumbing and bathroom fittings	
Repair category	1
Notes	No obvious defects were noted to plumbing or sanitary fitments.

Heating and hot water	
Repair category	1
Notes	The gas fired boiler is of a mid aged design and a boiler of this type should be kept on a regular maintenance contract and serviced by a Gas Safe engineer in order to maintain it in a satisfactory condition. Confirmation should be obtained to ascertain if the boiler is annually serviced. Documentary evidence of servicing by a Gas Safe engineer should be exhibited. (If no such contract exists then consideration should be given to have the boiler serviced by a Gas Safe engineer prior to entry).

Drainage	
Repair category	1
Notes	No obvious defects were noted.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	1
Roofing including roof space	1
Rainwater fittings	2
Main walls	2
Windows, external doors and joinery	2
External decorations	1
Conservatories/porches	-
Communal areas	2
Garages and permanent outbuildings	-
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	-
Internal decorations	1
Cellars	-
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	First	
2. Are there three steps or fewer to a main entrance door of the property?	Yes No X	
3. Is there a lift to the main entrance door of the property?	Yes No X	
4. Are all door openings greater than 750mm?	Yes No X	
5. Is there a toilet on the same level as the living room and kitchen?	Yes X No	
6. Is there a toilet on the same level as a bedroom?	Yes X No	
7. Are all rooms on the same level with no internal steps or stairs?	Yes X No	
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes X No	

4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

It is assumed that the tenure is absolute ownership. It is assumed that the property is unaffected by any planning or road proposals. It is assumed that the roads are adopted by the local authority for maintenance purposes.

The subjects are located in an area of past mining activity. A mining report should be obtained from the Coal Authority to ascertain past and future mining activity within the area.

Confirmation of any factoring agreement and/ or rights/ responsibilities for common repairs and apportionment of costs thereof. This should be clarified prior to sale/ purchase.

Our valuation below assumes that all necessary consents and approvals are available with respect to formation of the subjects in its current layout, in particular for formation of the subjects into its current layout, particularly for creation of bathroom from bed recesses.

It is understood that damp rot treatment works were carried out to the bathroom last year and all relevant guarantees for this work should be exhibited.

Estimated reinstatement cost for insurance purposes

We are of the opinion that the subjects should be insured for buildings reinstatement purposes for a sum of not less than £206,000 (TWO HUNDRED AND SIX THOUSAND POUNDS).

Valuation and market comments

Given the current market conditions and nature and location of the subjects, the property in its current condition could be fairly stated in the region of £115,000 (ONE HUNDRED AND FIFTEEN THOUSAND POUNDS).

Signed	Security Print Code [500152 = 6871] Electronically signed		
Report author	Alan Bain		
Company name	Hardies Property & Construction Consultants		
Address	Suite 1.02 The Innovation Centre, 1 Ainslie Road, Hillington Park, Glasgow, G52 4RU		

Date of report	18th August 2016
----------------	------------------

Mortgage Valuation Report



Property Address				
Address Seller's Name Date of Inspection	FLAT 1/1, 7 SPRINGBANK STREET, GLASGOW, G20 7EF MR GRANT DONNAN 16th August 2016			
Property Details				
Property Type	Purpose built flat Converted flat X Tenement flat	Converted maisonette Flat over non-residential use Other (specify in General Remarks)		
Property Style		End terrace Other (specify in General Remarks)		
Does the surveyor believe that the property was built for the public sector, e.g. local authority, military, police?				
Flats/Maisonettes onl Approximate Year of	No. of units in block 8	provided? Yes X No		
Tenure				
X Absolute Ownership	Leasehold Ground rent £ Unexpired years			
Accommodation				
Number of Rooms	1 Living room(s) 2 Bedroom(s) 1 Kitchen(s) 1 Bathroom(s) 0 WC(s) 0 Other (Specify in General remark			
Gross Floor Area (excluding garages and outbuildings) m² (Internal) 82 m² (External) Residential Element (greater than 40%) X Yes No				
Residential Element	(greater than 40%) X Yes No			
Garage / Parking /	Outbuildings			
Single garage Available on site?	☐ Double garage ☐ Parking space ☐ X No garaç	ge / garage space / parking space		
Permanent outbuildin				

Mortgage Valuation Report

Construction							
Walls	Brick	X Stone	Concre	te Timber fran	ne Oth	er (specify in Ger	neral Remarks)
Roof	X Tile	Slate	Asphal	t Felt	Oth	er (specify in Ger	neral Remarks)
Special Risks							
Has the property	suffered struc	tural movem	ent?			X Yes	No
If Yes, is this rece	nt or progres	sive?				Yes	X No
Is there evidence, immediate vicinity		ason to antic	cipate subsider	nce, heave, landsl	ip or flood in th	ne Yes	X No
If Yes to any of th	e above, prov	vide details ir	General Rem	arks.			
Service Connec	ctions						
Based on visual ir of the supply in G			vices appear to	be non-mains, pl	ease commen	t on the type a	and location
Drainage	X Mains	Private	None	Wate	er X Mains	Private	None
Electricity	X Mains	Private	None	Gas	X Mains	Private	None
Central Heating	X Yes	Partial	None				
Brief description of	of Central Hea	ating:					
Gas fired system	ı.						
Site							
Apparent legal iss	sues to be ver	rified by the o	conveyancer. I	Please provide a b	orief descriptio	n in General R	emarks.
Rights of way	X Shared dri	ves / access	Garage or of	her amenities on sepa	rate site X Sh	ared service conr	nections
Ill-defined boundar	ries	Agricu	Itural land include	d with property		her (specify in Ge	
Location							
Residential suburb	X Re	sidential within t	own / city	Mixed residential / con	nmercial Ma	ainly commercial	
Commuter village	Re	mote village		solated rural property	Ot	her (specify in Ge	neral Remarks)
Planning Issues	s						
Has the property I	been extende	d / converted	d / altered?	X Yes No			
If Yes provide det	ails in Genera	al Remarks.					
Roads							
X Made up road	Unmade roa	ıd Partly	y completed new r	oad Pedestri	an access only	Adopted	Unadopted

Mortgage Valuation Report

Retention recommended? Yes

Estimated cost of essential repairs £

X No

Amount £[

Mortgage Valuation Report

Comment on Mortgageal	bility	
The subjects form suitable	e security for normal lending purposes.	
Valuations		
Market value in present con Market value on completion Insurance reinstatement val (to include the cost of total r Is a reinspection necessary	of essential repairs lue rebuilding, site clearance, professional fees, ancillary charges plus VAT)	£ 115,000 £ 206,000
What is the reasonable rand month Short Assured Tenar	ge of monthly rental income for the property assuming a letting on a 6	£
	here there is a steady demand for rented accommodation of this type?	Yes No
Signed Surveyor's name Professional qualifications	Security Print Code [500152 = 6871] Electronically signed by:- Alan Bain MRICS	
Company name Address Telephone Fax	Hardies Property & Construction Consultants Suite 1.02 The Innovation Centre, 1 Ainslie Road, Hillington Park, Glasg 0141 585 6373	ow, G52 4RU

18th August 2016

Report date





Property Questionnaire



Property address	Flat 1/1, 7 Springbank Street Glasgow G20 7EF
Seller(s)	Grant Donnan
Completion date of property	11/08/16

questionnaire





Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

Information to be given to prospective buyer(s)

1.	Length of ownership			
	How long have you owned the property? 14 years			
2.	Council tax			
	Which Council Tax band is your property in? (Please tick)			
	A B C D E F G H			
3.	Parking			
	What are the arrangements for parking at your property? (Please tick all that apply)			
	• Garage □			
	Allocated parking space			
	• Driveway			
	Shared parking			
	• On street ⊠			
	Resident permit			
	Metered parking			
	Other (please specify):			
4.	Conservation area			
	Is your property in a designated Conservation Area (that is an Xies of special architectural or historical interest, the character or No appearance of which it is desirable to preserve or enhance)?			
5.	Listed buildings			
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	Yes No		



6.	Alterations/additions/extensions	
a.	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for examples provision of an extra bath/shower room, toilet, or bedroom? Don't least the below the changes which you have made:	now 🗆
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work? If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking. If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:	Yes No Don't know
b.	Have you had replacement windows, doors, patio doors or double glazing installed in your property? If you have answered yes, please answer the three questions below:	Yes No Don't know
	(i) Were the replacements the same shape and type as the ones you replaced?	Yes No Don't know
	(ii) Did this work involve any changes to the window or door openings?	Yes No Don't know
	(iii) Please describe the changes made to the windows doors, o approximate dates when the work was completed): Please give any guarantees which you received for this work to estate agent.	
7.	Central heating	
a.	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property — the main living room, the bedroom(s), the hall and the bathroom). If you have answered yes or partial – what kind of central	Partial
	heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas	



	warm air).		
	If you have answered yes, please answer the three questions below:		
	i) When was your central heating system or partial central heating system installed?	Yes No Don't know	
	(ii) Do you have a maintenance contract for the central heating system?	Yes No	
	If you have answered yes, please give details of the company with which you have a maintenance contract:	Don't know	
	(iii) When was your maintenance agreement last renewed? (Please provide the month and year).	Yes No Don't know	
8.	Energy Performance Certificate		
	Does your property have an Energy Performance Certificate which is less than 10 years old?	Yes No Don't know	
9.	Issues that may have affected your property		
a.	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	Yes No Don't know	
	If you have answered yes, is the damage the subject of any outstanding insurance claim?	Yes No Don't know	
b.	Are you aware of the existence of asbestos in your property?	Yes No	
	If you have answered yes, please give details:	Don't know	



	10.	Services				
	se tick	which services ar	e connected to your prop	erty and give details of	fthe	
Service	s		Connected	Supplier		
Gas or	liquid p	etroleum gas	Yes	EON		
Water r water s		r private	Mains	Glasgow City Coun	cil	
Electric	ity		Yes	EON		
Mains o	Irainag	e	Yes	Glasgow City Coun	cil	
Telepho	one					
Cable 1	V or sa	tellite				
Broadb	and					
	b.					
			tank system at your prop vered yes, please answer	_	Yes No Don't know	
		(i) Do you have a	appropriate consents for	the discharge from	Yes No Don't know	
		If you have answ	a maintenance contract f <u>vered yes,</u> please give de have a maintenance cont	tails of the company	Yes No Don't know	
	11.	•	for shared or common a			
	a.	anything used jo private road, bou If you have answ	f any responsibility to cont intly, such as the repair of indary, or garden area? <u>ered yes,</u> please give deta sts to common elements	a shared drive, ils: 7% share of	Yes No Don't know	
	b.	Is there a respon	sibility to contribute to rep	pair and maintenance		



	of the roof, common stairwell or other common areas? Yes	
	No	
	If you have answered yes, please give details: 7% share of Don't ke maintenance costs to common elements	now ⊔
C.	Has there been any major repair or replacement of any part of	Yes 🗵
	the roof during the time you have owned the property?	No 📙
d.	Do you have the right to walk over any of your neighbours'	Don't know ☐ Yes ☐
u.	property – for example to put out your rubbish bin or to	No 🗵
	maintain your boundaries?	Don't know
	•	
	If you have answered yes, please give details:	
	As far as you are aware, do any of your neighbours have the	Yes
	right to walk over your property, for example to put out their	No 🖾
	rubbish bin or to maintain their boundaries?	Don't know
e.		
	If you have answered yes, please give details:	
	As for as you are sware is there a public right of way seress	Yes
	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over	Yes □ □
	which the public has a right to pass, whether or not the land is	Don't know
f.	privately-owned.)	
	privately contour,	
	If you have answered yes, please give details:	
40		
12.	Charges associated with your property	N
a.	Is there a factor or property manager for your property?	Yes 🗵
	If you have an averaged year interest investigle the manner and address.	No 📙
	If you have answered yes, please provide the name and address,	Don't know ☐
	and give details of any deposit held and approximate charges: Queens Cross Factoring, 45 Firhill Road. Approx £50 per month	
	Queens 610331 actorning, 431 in init rioda. Approx 230 per month	
b.	Is there a common buildings insurance policy?	Yes 🗵
		No 📙
	If you have answered yes, is the cost of the insurance included in	Don't know □
	your monthly/annual factor's charges? Yes	
C.	Please give details of any other charges you have to pay on a regu	lar basis for the
	upkeep of common areas or repair works, for example to a resider	nts' association, or
	maintenance or stair fund. N/A	
13.	Specialist works	
a.	1	Yes
u.	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your	Yes □ □
	property?	Don't know



If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property. Dry rot repair work to timber floor joists at bathroom and adjacent bedroom, carried out by Alliance Timber & Damp Specialists Ltd December 2015		
As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?	Yes No Don't know	
If you have answered yes, please give details: Appropriate fungicidal woodpaste used and adjacent masonry walls treated as part of the above mentioned repair works.		
If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?	Yes No Don't know	
If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate.		
	whether you carried out the repairs (and when) or if they were done before you bought the property. Dry rot repair work to timber floor joists at bathroom and adjacent bedroom, carried out by Alliance Timber & Damp Specialists Ltd December 2015 As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property? If you have answered yes, please give details: Appropriate fungicidal woodpaste used and adjacent masonry walls treated as part of the above mentioned repair works. If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work? If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work	whether you carried out the repairs (and when) or if they were done before you bought the property. Dry rot repair work to timber floor joists at bathroom and adjacent bedroom, carried out by Alliance Timber & Damp Specialists Ltd December 2015 As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property? Whete rot, or damp ever been carried out to your property? Whete rot, or damp ever been carried out to your property? Whete rot, or damp ever been carried out to your property? Whete rot, or damp ever been carried out to your property? No Don't know If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work? Whete rot

14.	Guarantees					
a.	Are there any guarantees or warranties for any of the following:					
		No	Yes	Don't know	With title deeds	Lost
(i)	Electrical work			\boxtimes		
(ii)	Roofing			\boxtimes		
(iii)	Central heating			\boxtimes		
(iv)	National House Building Council (NHBC)			\boxtimes		
(v)	Damp course			\boxtimes		
(vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)					
b.	If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s):					
c.	Are there any outstanding claims under any of the guarantees listed above? Yes No If you have answered yes, please give details: Don't know					



15.	Boundaries	
	So far as you are aware, has any boundary of your property been moved in the last 10 years? Yes No If you have answered yes, please give details: Don't ke	now 🗆
16.	Notices that affect your property	Yes No Don't know
	In the past three years have you ever received a notice:	Yes
a.	advising that the owner of a neighbouring property has made a planning application?	Yes No Don't know
b.	that affects your property in some other way?	Yes No Don't know
c.	that requires you to do any maintenance, repairs or improvements to your property?	Yes □ No ⊠ Don't know □
	If you have answered yes to any of a-c above, please give the n solicitor or estate agent, including any notices which arrive at a date of entry of the purchaser of your property.	<u>-</u>

Declaration by the seller(s)/or other authorised body or person(s)

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s): Grant Donnan

Date: 11/08/16





EDINBURGH
London House, Ground Floor
20-22 East London Street
Edinburgh EH7 4BQ
Tel: 0131 557 9300 Fax: 0131 557 3520
Email: edinburgh@hardies.co.uk

ABERDEEN The Coach House, 68 Spademill Lane Aberdeen AB15 4EZ Tel: 01224 325596 Fax: 01224 323403 Email: aberdeen@hardies.co.uk

DALKEITH 19 South Street, Dalkeith EH22 1AH Tel: 0131 663 2780 Fax: 0131 660 4594 Email: dalkeith@hardies.co.uk

DUNDEE Whitehall House, 35 Yeaman Shore Dundee DD1 48U Tel: 01382 220699 Email: admin@christie-partners.co.uk

DUNFERMLINE
The Signature Building, 8 Pitreavie Court
Dunfermline KY11 8UU
Tel: 01383 731841 Fax: 01383 739714
Email: dunfermline@hardies.co.uk

GALASHIELS Anderson Chambers, Market Street Galashiels TD1 3AF Tel: 01896 668875 / 01896 755879 Email: galashiels@hardies.co.uk

GLASGOW
Suite 1.31, The Innovation Centre
1 Ainslie Road, Hillington Park
Glasgow G52 4RU
Tel: 0141 585 6373 Fax: 0141 585 6372
Email: glasgow@hardies.co.uk

29 Brandon Street, Hamilton ML3 6DA Tel: 01698 421214 Fax: 0141 585 6372 Email: hamilton@hardies.co.uk HELENSBURGH 15-17 Colquhoun Street Helensburgh G84 8AN Tel: 01436 678181 Fax: 0141 585 6372 Email: helensburgh@hardies.co.uk

KILMARNOCK 35 Main Street, Stewarton Kilmarnock KA3 5BS Tel: 01560 480354 Fax: 0141 585 6372 Email: kilmarnock@hardies.co.uk

PAISLEY
Mirren Court 1, 119 Renfrew Road
Paisley PA3 4EA
Tel: 0141 887 4240 Fax: 0141 585 6372
Email: paisley@hardies.co.uk

PERTH
Old Academy Buildings
7 Rose Terrace, Perth PH1 5HA
Tel: 01738 631631 Fax: 01738 637768
Email: perth@hardies.co.uk

ST ANDREWS Swilken House, 35 Largo Road St Andrews KY16 8NJ Tel: 01334 476469 Fax: 01334 477779 Email: standrews@hardies.co.uk

STIRLING 10 Viewfield Place, Stirling FK8 1NQ Tel: 01786 474476 Fax: 01786 448305 Email: stirling@hardies.co.uk

In association with WJR Christie & Partners LLP Whitehall House 35 Yearnan Shore DUNDEE DD1 48U

www.hardies.co.uk