"THE NATIONAL PROPERTY SERVICE"



Shepherd Chartered Surveyors



Flat 3/1 60 Wilson Street Glasgow G1 1HD



Energy performance certificate



Energy Performance Certificate (EPC)

Scotland

Dwellings

FLAT 3/1 WILSON COURT, 60 WILSON STREET, GLASGOW, G1 1HD

Dwelling type:	Mid-floor flat
Date of assessment:	12 May 2017
Date of certificate:	15 May 2017
Total floor area:	50 m ²
Primary Energy Indicator:	213 kWh/m ² /year

Reference number: Type of assessment: Approved Organisation: Main heating and fuel:

0190-2032-3050-9593-5505 RdSAP, existing dwelling Elmhurst Room heaters, electric

You can use this document to:

B

Not environmentally friendly - higher CO₂ emissions

(81-91)

(69-80)

(55-68)

(39-54

(21-38)


(1-20)

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£1,629	See your recommendations
Over 3 years you could save*	£717	report for more information

* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions

75



D

Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band C (72)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band C (75)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

74

Recommended measures	Indicative cost	Typical savings over 3 years	Available with Green Deal
1 Low energy lighting	£25	£36.00	
2 High heat retention storage heaters	£1,200 - £1,800	£675.00	\bigcirc

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.



The Green Deal may allow you to make your home warmer and cheaper to run at no up-front capital cost. See your recommendations report for more details.

F

G

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

FLAT 3/1 WILSON COURT, 60 WILSON STREET, GLASGOW, G1 1HD 15 May 2017 RRN: 0190-2032-3050-9593-5505

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Sandstone or limestone, with internal insulation Solid brick, as built, insulated (assumed)	★★★★☆ ★★★★☆	★★★★☆ ★★★★☆
Roof	(another dwelling above)	—	
Floor	(another dwelling below)	—	
Windows	Fully double glazed	★★★☆☆	★★★☆☆
Main heating	Room heaters, electric	****	★★☆☆☆
Main heating controls	Appliance thermostats	★★★☆☆	★★★★☆
Secondary heating	Room heaters, electric	—	_
Hot water	Electric immersion, standard tariff	****	★★☆☆☆
Lighting	Low energy lighting in 44% of fixed outlets	★★★☆☆	★★★☆☆

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 36 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 1.8 tonnes of carbon dioxide every year. You could reduce emissions by switching to renewable energy sources.

Estimated energy of	osts for this home		
	Current energy costs	Potential energy costs	Potential future savings
Heating	£699 over 3 years	£393 over 3 years	
Hot water	£753 over 3 years	£393 over 3 years	You could
Lighting	£177 over 3 years	£126 over 3 years	save £717
Totals	£1,629	£912	over 3 years

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

De			Typical saving	Rating after improvement		Green
Re	commended measures	Indicative cost	per year	Energy	Environment	Deal
1	Low energy lighting for all fixed outlets	£25	£12	C 73	C 75	
2	High heat retention storage heaters and dual immersion cylinder	£1,200 - £1,800	£225	B 84	C 74	\bigcirc

Measures which have a green deal tick \bigcirc are likely to be eligible for Green Deal finance plans based on indicative costs. Subsidy also may be available for some measures, such as solid wall insulation. Additional support may also be available for certain households in receipt of means tested benefits. Measures which have an orange tick \bigcirc may need additional finance. To find out how you could use Green Deal finance to improve your property, visit www.greenerscotland.org or contact the Home Energy Scotland hotline on 0808 808 2282.

Alternative measures

There are alternative improvement measures which you could also consider for your home. It would be advisable to seek further advice and illustration of the benefits and costs of such measures.

- Biomass boiler (Exempted Appliance if in Smoke Control Area)
- Air or ground source heat pump

Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.



About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Low energy lighting

Replacement of traditional light bulbs with energy saving recommended ones will reduce lighting costs over the lifetime of the bulb, and they last up to 12 times longer than ordinary light bulbs. Also consider selecting low energy light fittings when redecorating; contact the Lighting Association for your nearest stockist of Domestic Energy Efficient Lighting Scheme fittings.

2 High heat retention storage heaters

Modern storage heaters are less expensive to run than the direct acting, on-peak heating system in the property. A dual-rate electricity supply is required to provide the off-peak electricity that these heaters use; this is easily obtained by contacting the energy supplier. Ask for a quotation for high heat retention heaters with automatic charge and output controls. A dual-immersion cylinder, which can be installed at the same time, will provide cheaper hot water than the system currently installed. Installations should be in accordance with the national wiring standards. Building regulations generally apply to this work and a building warrant may be required, so it is best to obtain advice from your local authority building standards department and from a gualified electrical heating engineer. Ask the heating engineer to explain the options, which might also include switching to other forms of electric heating.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

You could receive Renewable Heat Incentive (RHI) payments and help reduce carbon emissions by replacing your existing heating system with one that generates renewable heat and, where appropriate, having your loft insulated and cavity walls filled. The estimated energy required for space and water heating will form the basis of the payments. For more information go to www.energysavingtrust.org.uk/scotland/rhi.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	1,496	N/A	N/A	N/A
Water heating (kWh per year)	1,612			

FLAT 3/1 WILSON COURT, 60 WILSON STREET, GLASGOW, G1 1HD 15 May 2017 RRN: 0190-2032-3050-9593-5505

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Assessor membership number:	Mr. Gerry Brady EES/020019
Company name/trading name:	J & E Shepherd
Address:	13 Albert Square
	Dundee
	DD1 1XA
Phone number:	01382200454
Email address:	g.brady@shepherd.co.uk
Related party disclosure:	No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Opportunity to benefit from a Green Deal on this property

Under a Green Deal, the cost of the improvements is repaid over time via a credit agreement. Repayments are made through a charge added to the electricity bill for the property.

To see which improvements are recommended for this property, please turn to page 3. You can choose which improvements you want to install and ask for a quote from an authorised Green Deal provider. They will organise installation by an authorised Green Deal installer. If you move home, the responsibility for paying the Green Deal charge under the credit agreement passes to the new electricity bill payer.

For householders in receipt of income-related benefits, additional help may be available.

To find out more, visit www.greenerscotland.org or call 0808 808 2282.



Scottish Single Survey



survey report on:

Property address	Flat 3/1 Wilson Court 60 Wilson Street GLASGOW G1 1HD
------------------	--

Customer address	Flat 3/1 Wilson Court 60 Wilson Street GLASGOW G1 1HD
------------------	--

Prepared by	J & E Shepherd
-------------	----------------

Date of inspection	12th May 2017
--------------------	---------------



PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property¹.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in the expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

¹ Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions. The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:-

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report² will be from information contained in the Report and the generic Mortgage Valuation Report.

² Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;

- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1. <u>Category 3:</u> Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2. <u>Category 2:</u> Repairs or replacement requiring future attention, but estimates are still advised.
- 3. <u>Category 1:</u> No immediate action or repair is needed.

WARNING:

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value, the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	The subjects comprise a purpose built flat on the third floor of a four storey and attics, Merchant City, block.
Accommodation	Third Floor: Entrance Hall, Living Room/Kitchen, Bedroom 1, Bedroom 2, Bathroom.
Gross internal floor area (m²)	50 sq.m.
Neighbourhood and location	The property is situated within Glasgow town centre in the Merchant City district. This area is developed by a variety of low rise flats and commercial premises. All local services and amenities are available nearby.
Age	Originally constructed circa 1900, converted in the 1980's.
Weather	Dry and bright.
Chimney stacks	None.
Roofing including roof space	 Sloping roofs were visually inspected with the aid of binoculars where appropriate. Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally. Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so. The roof is pitched and slated.

	Inspection of the common roof void is considered outwith the scope of this inspection due to health and safety considerations. In particular, the location of the roof space hatch within the common close stairwell and the regulations governing the inspection of confined spaces.
Rainwater fittings	Visually inspected with the aid of binoculars where appropriate.
	Parapet gutters and PVC gutters discharging into concealed downpipes and PVC downpipes.

Main walls	Visually inspected with the aid of binoculars where appropriate. Foundations and concealed parts were not exposed or inspected.
	The external walls are 600mm solid stone to the front elevation and 600mm brick and rendered to the rear elevation.

Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
	The windows are timber framed double glazed units.
	The entrance door to the flat is solid timber.

External decorations	Visually inspected.
	Gloss painted finishes to the window frames.

Conservatories / porches	None.	
Communal areas	Circulation areas visually inspected.	
	Typical common foyer with lift access.	
Garages and permanent outbuildings	None.	

Outside areas and boundaries	Visually inspected.
	Common rear yard.

Ceilings	Visually inspected from floor level.
	The ceilings are of plasterboard.
Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	The internal walls are dry lined with plasterboard.
Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted

Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch. Floors are suspended timber.

"head and shoulders" inspection at the access point.

There is a flat below. There is no sub floor area.

Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
	Timber skirtings and facings with light oak veneer timber internal doors with aluminium ironmongery.
	The kitchen is fitted with matt white wall and base units and wood block worktop.

Chimney breasts and fireplaces	None.
Internal decorations	Visually inspected.
	Emulsion finishes to the walls and ceilings with gloss painted finishes and natural wood finishes to the internal joinery.

Cellars	None.
Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on. A mains electricity supply is connected.

Gas	No supply.
Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	Where visible the plumbing system is run in modern copper piping and PVC wastes.
	The sanitary fittings comprise a three piece white suite of bath, WC and wash hand basin. There is a shower at the bath head.
Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.


Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.
	No tests whatsoever were carried out to the system or appliances.
	Hot water is provided by means of an electric immersion heater.
	There is no central heating system. There are electric, wall mounted, panel radiators within the principal apartments which appear to be mains operated and not an off peak system.

Drainage	Drainage covers etc. were not lifted.
	Neither drains nor drainage systems were tested.
	Foul and storm drainage are assumed to be connected to the main sewer.

Fire, smoke and burglar alarms	Visually inspected.
	No tests whatsoever were carried out to the system or appliances.
	The property has the benefit of a smoke alarm. There is no intruder alarm system to the flat itself, however, there is an electronic entry security intercom to the building.

Any additional limits to inspection	For flats / maisonettes
	Only the subject flat and internal communal areas giving access to the flat were inspected.
	If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation.
	The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.

The property is a family home and consequently the property contains furnishings, wall hangings, floor coverings, owners' belongings and storage within cupboards. These items have not been moved.
There is no sub floor area.
Access to the common roof space is outwith the scope of this inspection due to health and safety considerations.
All of the concealed areas are assumed to be free from significant defect.
An inspection for Japanese Knotweed was not carried out. This is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. It is therefore assumed that there is no Japanese Knotweed within the boundaries of the property or its neighbouring property. Identification of Japanese Knotweed is best undertaken by a specialist contractor.



2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	

Structural movement	
Repair category	1
Notes	No evidence of significant structural movement noted.

Dampness, rot and infestation	
Repair category	1
Notes	No defects of this nature noted within the curtilage of the flat. No evidence of significant condensation was noted at the date of inspection, however, it should be noted that this can alter due to varying weather conditions and the occupation usage of the property.

Chimney stacks	
Repair category	-
Notes	None.

Roofing including roof space	
Repair category	1
Notes	From our external ground level inspection, the roof covering appeared generally in fair repair, consistent with the property's type and age. The common roof void has not been inspected and is assumed to be free from material defect.

Rainwater fittings	
Repair category	1
Notes	It was dry at the date of inspection. There was no staining to the surrounding building fabric to indicate the presence of any leaks to the rainwater goods.

Main walls	
Repair category	1
Notes	A degree of weathering and erosion was noted to the external walls but this is consistent with the buildings age.

Windows, external doors and joinery	
Repair category	1
Notes	The flat contains timber framed double glazed units. Whilst there was no obvious defect on the date of our inspection, it should be appreciated that double glazed sealed units do have a limited life expectancy and defective seals can lead to condensation between the panes necessitating replacement of the unit. This can sometimes only be obvious during adverse weather conditions. No reportable defect noted to the entrance door.

External decorations	
Repair category	1
Notes	External paintwork should be maintained on a regular basis in order to prevent deterioration of timbers and metalwork.

Conservatories/porches	
Repair category	-
Notes	None.

Communal areas	
Repair category	1
Notes	No reportable defect noted to the common areas.

Garages and permanent outbuildings	
Repair category	-
Notes	None.

Outside areas and boundaries	
Repair category	1
Notes	No reportable defect noted to the site.

Ceilings	
Repair category	1
Notes	We noted no evidence of significant defect to the ceilings.

Internal walls	
Repair category	1
Notes	No evidence of significant defect noted to the internal walls at the visible areas.

Floors including sub-floors	
Repair category	1
Notes	The floors were obscured by tightly fitted floor coverings, however, the floors were noted to be relatively level with no significant loose or uneven flooring noted.

Internal joinery and kitchen fittings	
Repair category	1
Notes	The internal joinery appeared generally in fair repair. The kitchen is fitted with an ample number of serviceable wall and base units.

Chimney breasts and fireplaces	
Repair category	-
Notes	None.

Internal decorations	
Repair category	1
Notes	Minor wear and tear was noted to the internal decorations which are generally in neutral colours throughout.

Cellars	
Repair category	-
Notes	None.

Electricity	
Repair category	2
Notes	The electric wiring system appears to be PVC cabling, however, the fuse box is of an older design and some upgrading of the system may be required. It should be noted that only brand new or recently rewired properties will fully comply with the most up to date IET regulations.

Gas	
Repair category	-
Notes	No supply.

Water, plumbing and bathroom fittings	
Repair category	1
Notes	At the date of inspection the visible plumbing system appeared to be run in modern copper piping with PVC wastes.
	The sanitary fittings are all modern and all appear serviceable.

Heating and hot water	
Repair category	1
Notes	There is no heritable form of central heating. The electric panel heaters were not tested during the course of the inspection.

Drainage	
Repair category	1
Notes	We noted no evidence of ponding water to indicate defects to the surface water drainage and we would clearly state that inspection covers have not been raised and the drainage systems have not been tested.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	-
Roofing including roof space	1
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	1
External decorations	1
Conservatories/porches	-
Communal areas	1
Garages and permanent outbuildings	-
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	-
Internal decorations	1
Cellars	-
Electricity	2
Gas	-
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Third
2. Are there three steps or fewer to a main entrance door of the property?	Yes No X
3. Is there a lift to the main entrance door of the property?	Yes X No
4. Are all door openings greater than 750mm?	Yes X No
5. Is there a toilet on the same level as the living room and kitchen?	Yes X No
6. Is there a toilet on the same level as a bedroom?	Yes X No
7. Are all rooms on the same level with no internal steps or stairs?	Yes X No
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes No X

4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

It is assumed that tenure is Absoloute Ownership.

It is assumed that the property is unaffected by any planning or road proposals.

It is assumed that the road fronting the property is adopted by the Local Authority.

It is assumed that the common repair liability has been equitably apportioned.

Where defects or repairs have been identified within this report it is recommended that, prior to entering into any legally binding sale or purchase contract, further specialists or contractors advice and estimates should be obtained, to establish the implications, if any, on a potential offer to purchase or the sale price likely to be achieved for the property.

Estimated reinstatement cost for insurance purposes

The current cost of reinstating the property in its present form is estimated for insurance purposes to be approximately £160,000 (ONE HUNDRED AND SIXTY THOUSAND POUNDS).

Valuation and market comments

In our opinion, the Market Value as at 12th May 2017 of the heritable subjects described herein, with vacant possession, in their present condition, can be fairly stated in the sum of £165,000 (ONE HUNDRED AND SEVENTY FIVE THOUSAND POUNDS).

This report is provided in accordance with the Conditions of Engagement supplied.

This report is not the product of a building survey and all defects and other matters should be fully considered and, where appropriate, be the subject of specialist and tradesmen's reports prior to the conclusion of Missives.

Signed	Security Print Code [492240 = 7651] Electronically signed	
Report author	G T Brady	
Company name	J & E Shepherd	
Address	Suite 5B, St James Business Centre, Linwood Road, Paisley, PA3 3AT	

 Date of report
 24th May 2017

Mortgage Valuation Report



Property Address	
Address Seller's Name Date of Inspection	Flat 3/1 Wilson Court, 60 Wilson Street, GLASGOW, G1 1HD Ms A Stewart 12th May 2017
Property Details	
Property Type	House Bungalow Purpose built maisonette Converted maisonette Purpose built flat X Converted flat Tenement flat Flat over non-residential use Other (specify in General Remarks)
Property Style	Detached Semi detached Mid terrace End terrace Back to back High rise block X Low rise block Other (specify in General Remarks)
Does the surveyor be e.g. local authority, m	lieve that the property was built for the public sector, Yes X No ilitary, police?
Flats/Maisonettes only	No. of units in block 20
Approximate Year of	
Tenure	
X Absolute Ownership	Leasehold Ground rent £ Unexpired years
Accommodation	
Number of Rooms	1 Living room(s)2 Bedroom(s)1 Kitchen(s)1 Bathroom(s)0 WC(s)0 Other (Specify in General remarks)
Gross Floor Area (exc	cluding garages and outbuildings) 50 m ² (Internal) 65 m ² (External)
Residential Element (greater than 40%) X Yes No
Garage / Parking / Garage / Garage / Parking / Garage	Outbuildings
Single garage Available on site?	Double garage Parking space X No garage / garage space / parking space Yes No
Permanent outbuilding	gs:
None.	

Mortgage Valuation Report

Construction							
Walls	Brick	X Stone	Concrete	Timber frame	Other (specify in General Remarks)		
Roof	Tile	X Slate	Asphalt	Felt	Othe	er (specify in Gen	eral Remarks)
Special Risks							
Has the property s	suffered strue	ctural movem	ent?			Yes	X No
If Yes, is this recent or progressive?							No
Is there evidence, immediate vicinity		eason to antic	ipate subsidence	, heave, landslip o	or flood in the	e Yes	X No
If Yes to any of the above, provide details in General Remarks.							
Service Connec	tions						
Based on visual inspection only. If any services appear to be non-mains, please comment on the type and location of the supply in General Remarks.							
Drainage	X Mains	Private	None	Water	X Mains	Private	None
Electricity	X Mains	Private	None	Gas	Mains	Private	X None
Central Heating	Yes	Partial	X None				
Brief description of Central Heating:							
Site							
Apparent legal issues to be verified by the conveyancer. Please provide a brief description in General Remarks.							
Rights of way	X Shared dri	-		amenities on separate		red service conn	
III-defined boundar			Itural land included w			er (specify in Ge	
Location							
Residential suburb	X Re	esidential within t	own / city 📃 Mixe	ed residential / comme	rcial 🗌 Mai	nly commercial	
Commuter village	Re	emote village	Sola Isola	ated rural property	Oth	er (specify in Ge	neral Remarks)
Planning Issues	6						
Has the property t	been extende	ed / converted	/ altered? X	Yes 🗌 No			
If Yes provide details in General Remarks.							
Roads							
X Made up road	Unmade roa	ad Partly	<pre>/ completed new road</pre>	Pedestrian a	access only	Adopted	Unadopted

Mortgage Valuation Report

General Remarks

The subjects comprise a third floor flat within a five storey block situate in the Merchant City district in the heart of Glasgow. This is a mixed residential/commercial area with all local services and amenities available nearby.

The original building dates from around 1900, however the property was converted to residential flats in the 1990's.

At the date of inspection the building fabric appeared to have been maintained generally in fair repair, consistent with the property's type and age.

Essential Repairs

None.	
Estimated cost of essential repairs £	Retention recommended? Yes No Amount £

Mortgage Valuation Report

Comment on Mortgageability

The subjects form	an adequate mortgag	ae security in their	present condition.

Valuations	
Market value in present condition	£ 175,000
Market value on completion of essential repairs	£
Insurance reinstatement value (to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT)	£ 160,000
Is a reinspection necessary?	Yes X No
Buy To Let Cases	
What is the reasonable range of monthly rental income for the property assuming a letting on a 6 month Short Assured Tenancy basis?	£
Is the property in an area where there is a steady demand for rented accommodation of this type?	Yes No

Declaration	
Signed	Security Print Code [492240 = 7651] Electronically signed by:-
Surveyor's name	G T Brady
Professional qualifications	BSc FRICS
Company name	J & E Shepherd
Address	Suite 5B, St James Business Centre, Linwood Road, Paisley, PA3 3AT
Telephone	0141 889 8334
Fax	0141 889 4384
Report date	24th May 2017







GLASGOW, G1 1HD	
Seller(s) Purple Bricks	
Completion date of property questionnaire 2/05/2017	




Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

Information to be given to prospective buyer(s)

1. Length of ownership

	How long have you owned the property?	10	
2.	Council tax		
	Which Council Tax band is your property in?	d	
3.	Parking		
	What are the arrangements for parking at your property?	Resident permit	
4.	Conservation area		
	Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?	don't know	
5.	Listed buildings		
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	yes	
6.	Alterations/additions/extensions		
a)	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)? If you have answered yes, please describe below the changes which you have made:	no	
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work? If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking. If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:	#	
b)	Have you had replacement windows, doors, patio doors or double glazing installed in your property? If you have answered yes, please answer the three questions below:	yes	
	(i) Were the replacements the same shape and type as the ones you replaced?	yes	





	If you have answered yes, please give details:	The building uses James Gibb as a factor. This is billed quartet.
c)	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?	yes
d)	Do you have the right to walk over any of your neighbours property - for example to put out your rubbish bin or to maintain your boundaries?	no
e)	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?	no
f)	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privatel-owned.)	no
12.	Charges associated with your property	
a)	Is there a factor or property manager for your property?	yes
	If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:	James Gibb - 65 Greendyke Street, Glasgow, G15PX Approx: £230 per quarter
b)	Is there a common buildings insurance policy?	yes
	If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges?	yes
c)	Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.	
13.	Specialist works	
a)	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?	yes
	If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property:	
	If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges?:	The repairs were carried out on the whole building, not the property as such - this was conducted by the factor at the time Grant and Wilson, but James Gibb should have the details.
b)	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?	yes
	If you have answered yes, please give details:	All details with James Gibb



c)	If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work? If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate.	no
	Guarantees are held by:	I believe these will be held by James Gibb
14.	Guarantees	
a)	Are there any guarantees or warranties for any of the following:	
i)	Electrical work	dont know
ii)	Roofing	dont know
iii)	Central Heating	no
iv)	National House Building Council (NHBC)	dont know
v)	Damp course	dont know
b)	If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s):	
c)	Are there any outstanding claims under any of the guarantees listed above?	no
15.	Boundaries	
	So far as you are aware, has any boundary of your property been moved in the last 10 years?	no

16.	Notices that affect your property In the past three years have you ever received a notice:	
a)	advising that the owner of a neighbouring property has made a planning application?	no
b)	that affects your property in some other way?	no
c)	that requires you to do any maintenance, repairs or improvements to your property?	no
	If you have answered yes to any of the above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of	

Declaration by the seller(s)/or other authorised body or person(s)

the purchaser of your property.

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s)

Alison Stewart

Date

SHEPHERD

2/05/2017

Shepherd Offices

Aberdeen: 01224 202800 Ayr: 01292 267987 Coatbridge: 01236 436561 Cumbernauld: 01236 780000 Dumbarton: 01389 731682 Dumfries: 01387 264333 Dundee: 01382 200454

East Kilbride: 01355 248535 Edinburgh: 0131 2251234 Falkirk: 01324 635999 Fraserburgh: 01346 517456 Forfar: 01307 466100 Galashiels: 01896 750150 Glasgow: 0141 3532080

Dunfermline: 01383 722337 Glasgow (Southside): 0141 649 8020 Greenock: 01475 730717 Hamilton: 01698 897548 Inverness: 01463 712239 Kilmarnock: 01563 520318 Kirkcaldy: 01592 205442 Livingston: 01506 416777 Montrose: 01674 676768

Motherwell: 01698 252229 Musselburgh: 0131 6533456 Paisley: 0141 8898334 Perth: 01738 638188 Peterhead: 01779 470766 Saltcoats: 01294 464228 St Andrews: 01334 477773 Stirling: 01786 450438







Tel: 0845 263 7995

www.shepherd.co.uk

Tel: 0845 263 7995