# YOUR ONESURVEY HOME REPORT

### ADDRESS

2/2 24 Meadowpark Street Glasgow G31 2RX

### PREPARED FOR

Harry McGinn

#### **INSPECTION CARRIED OUT BY:**

#### HOME REPORT GENERATED BY:





# **Document Index**

Document	Status	Prepared By	Prepared On
Index of Documents			
Single Survey	Final	Glasgow North - Allied Surveyors Scotland Plc	30/05/2017
Mortgage Certificate	Final	Glasgow North - Allied Surveyors Scotland Plc	30/05/2017
Property Questionnaire	Final	Mr. Harry McGinn	
EPC	File Uploaded	Glasgow North - Allied Surveyors Scotland Plc	07/09/2016

### **Important Notice:**

This report has been prepared for the purposes of and use of Harry McGinn. Should your name not be on this report then Onesurvey is unable to guarantee that this is a genuine or complete copy of the Home Report. A personalised copy of this Home Report may be obtained at www.onesurvey.org free of charge.

If you are a potential purchaser of this property you may then present your personalised copy of the report to your advisers or mortgage provider with a view to them requesting a transcription report from the appointed Chartered Surveyor.

Neither the whole, nor any part of this report may be included in any published document, circular or statement, nor published in any way without the consent of Onesurvey Ltd. Only the appointed Chartered Surveyor can utilise the information contained herein for the purposes of providing a transcription report for mortgage/loan purposes



# SINGLE Survey

A report on the condition of the property, with categories being rated from 1 to 3.



# Single Survey

### Survey report on:

Surveyor Reference	GD/4608
--------------------	---------

Customer	Mr. Harry McGinn
----------	------------------

Customer address	2/2 24 Meadowpark Street Glasgow G31 2RX
------------------	---

Date of Re- inspection	26/05/2017
---------------------------	------------

Date of Original Inspection	05/09/2016
--------------------------------	------------

Prepared by	Hugh G Campbell Glasgow North - Allied Surveyors Scotland Plc
-------------	--

#### PART 1 - GENERAL

#### 1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property. <sup>1</sup>

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

 $\overline{\mathcal{M}}$ 

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

#### 1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

<sup>&</sup>lt;sup>1</sup> Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Codes of Conduct

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

#### 1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

#### 1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

#### 1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report. 2

#### 1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

#### 1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

#### 1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for

expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

#### 1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

#### 1.10 **DEFINITIONS**

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format.
- the "Market Value" is The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property.
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and

<sup>2</sup> Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Rules of Conduct.

- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

#### PART 2 – DESCRIPTION OF THE REPORT

#### 2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

#### 2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, *visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.* 

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

#### 2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not

significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 2.3.1 <u>Category 3</u>: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2.3.2 <u>Category 2</u>: Repairs or replacement requiring future attention, but estimates are still advised.
- 2.3.3 <u>Category 1</u>: No immediate action or repair is needed.

**WARNING**: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

#### 2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

#### 2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

#### 2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

#### 2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- \*There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- \*There are no particularly troublesome or unusual legal restrictions;
- \*There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property

### **1. INFORMATION AND SCOPE OF INSPECTION**

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the Surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the Surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the Surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities will not be inspected or reported on.

Description	Second floor flat in four storey tenement building containing seven flats.
Accommodation	SECOND FLOOR: Entrance hall, lounge (front), bedroom one (front), bedroom two (rear), kitchenette (internal), shower room (internal) with usual fittings including wc.
Gross internal floor area (m2)	46 sq.metres.
Neighbourhood and location	The property is located in Dennistoun, in the east end of Glasgow. The surrounding area is developed with properties of varying age and character. All usual residential amenities are available within a radius of half a mile.
Age	The property was built about 1880.
Weather	At the time of inspection, it was dry and bright.
Chimney stacks	Chimney stacks are of cement rendered brickwork.
	Where visible, roof flashings are of lead. Visually inspected with the aid of binoculars where required.
Roofing including roof space	The roof is pitched, timber framed boarded felted and has been retiled.
	The roof space area is insulated with fibreglass material between and over ceiling joists and inspection was consequently restricted to what could be seen from the access hatch at the top of the common stairwell. Sloping roofs were visually inspected with the aid of binoculars

	where required.
	Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.
Rainwater fittings	There is a wallhead type of gutter at the front of the building which could not be seen from ground level. The rear gutter is plastic. Downpipes are plastic and cast iron.
	Visually inspected with the aid of binoculars where required.
Main walls	The outer walls to the property are constructed of 600mm grey sandstone which has been rendered with a smooth render to the front and with roughcast to the rear.
	Visually inspected with the aid of binoculars where required. Foundations and concealed parts were not exposed or inspected.
Windows, external doors and joinery	Windows have been replaced with timber framed pivot style double glazed units.
	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
External decorations	External woodwork and ironwork are painted.
External decorations	External woodwork and ironwork are painted. <i>Visually inspected.</i>
External decorations Conservatories / porches	
Conservatories /	Visually inspected.
Conservatories / porches	Visually inspected.     There are none.     There is a common stairwell area. There are two flats at ground floor level, one at the first floor landing, two at the
Conservatories / porches	Visually inspected.     There are none.     There is a common stairwell area. There are two flats at ground floor level, one at the first floor landing, two at the second floor landing and two at the top floor landing.
Conservatories / porches	Visually inspected.     There are none.     There is a common stairwell area. There are two flats at ground floor level, one at the first floor landing, two at the second floor landing and two at the top floor landing.     There are timber framed single glazed windows to the rear.
Conservatories / porches Communal areas Garages and permanent	Visually inspected.     There are none.     There is a common stairwell area. There are two flats at ground floor level, one at the first floor landing, two at the second floor landing and two at the top floor landing.     There are timber framed single glazed windows to the rear.     The walls of the stairwell are painted.
Conservatories / porches Communal areas Garages and	Visually inspected.     There are none.     There is a common stairwell area. There are two flats at ground floor level, one at the first floor landing, two at the second floor landing and two at the top floor landing.     There are timber framed single glazed windows to the rear.     The walls of the stairwell are painted.     Circulation areas visually inspected.     There is a shared bin store in the drying green area at the
Conservatories / porches Communal areas Garages and permanent	Visually inspected.     There are none.     There is a common stairwell area. There are two flats at ground floor level, one at the first floor landing, two at the second floor landing and two at the top floor landing.     There are timber framed single glazed windows to the rear.     The walls of the stairwell are painted.     Circulation areas visually inspected.     There is a shared bin store in the drying green area at the rear of the building.
Conservatories / porches Communal areas Garages and permanent outbuildings Outside areas and	Visually inspected.     There are none.     There is a common stairwell area. There are two flats at ground floor level, one at the first floor landing, two at the second floor landing and two at the top floor landing.     There are timber framed single glazed windows to the rear.     The walls of the stairwell are painted.     Circulation areas visually inspected.     There is a shared bin store in the drying green area at the rear of the building.     Visually inspected.     There is a drying green area to the rear which is enclosed
Conservatories / porches Communal areas Garages and permanent outbuildings Outside areas and	Visually inspected.There are none.There is a common stairwell area. There are two flats at ground floor level, one at the first floor landing, two at the second floor landing and two at the top floor landing.There are timber framed single glazed windows to the rear.The walls of the stairwell are painted.Circulation areas visually inspected.There is a shared bin store in the drying green area at the rear of the building.Visually inspected.There is a drying green area to the rear which is enclosed with fences and walls.

	plasterboard.
	Visually inspected from floor level.
Internal walls	The internal walls are partly hard plastered, partly strapped and plastered and partly plasterboard.
	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
Floors including sub floors	Floors are of suspended timber construction, overlaid with tongue and grooved boarding.
	Inspection of floor surfaces was completely prevented by floor coverings and furniture.
	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
Internal joinery and kitchen fittings	The internal woodwork is of a type and style typical of a tenement flat of this age. Some renewals have been carried out in the past.
	In the kitchenette, there is a sink unit and there are storage units.
	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
Chimney breasts and	The original fireplaces in the flat have been sealed.
fireplaces	Visually inspected. No testing of the flues or fittings was carried out.
Internal decorations	Walls and ceilings are papered and painted.
	Visually inspected.
Cellars	There are none.
Electricity	Electricity is from mains supply. At the distribution board, which is wall mounted in the entrance hall, there are circuit breakers.
	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will state that in the report and will not turn them on.
Gas	Gas is from mains supply. The gas meter is wall mounted in the entrance hall.
	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet

	state that in the report and will not turn them on
	state that in the report and will not turn them on.
Water, plumbing and bathroom fittings	Water is from public supply. Plumbing, where visible, is copper, plastic and steel.
	There is a white three piece suite in the shower room.
	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
Heating and hot water	There is a gas fired central heating system in the property. There is an Ideal central heating boiler located in a cupboard in the rear bedroom.
	Hot water is from the central heating boiler.
	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.
	No tests whatsoever were carried out to the system or appliances.
Drainage	Drainage is assumed to mains sewer.
	Drainage covers etc were not lifted.
	Neither drains nor drainage systems were tested.
Fire, smoke and burglar	There are smoke alarms.
alarms	Visually inspected.
	No tests whatsoever were carried out to the system or appliances.
Any additional limits to inspection	Only the subject flat and internal communal areas giving access to the flat were inspected.
	If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the Surveyor will assume that there are no defects that will have a material effect on the valuation.
	The building containing the flat, including any external communal areas, was visually inspected only to the extent that the Surveyor is able to give an opinion on the general condition and standard of maintenance.
	An inspection for Japanese Knotweed was not carried out. This is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. It is therefore assumed that there is no Japanese Knotweed within the boundaries of the property or its neighbouring property. Identification of Japanese Knotweed is best undertaken by a specialist contractor. If it exists removal must be undertaken in a controlled manner by specialist contractors. This can prove to be expensive.

### Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

	1	Chimney pots
	2	Coping stone
	3	Chimney head
	4	Flashing
	5	Ridge ventilation
	6	Ridge board
	1	Slates / tiles
	8	Valley guttering
	9	Dormer projection
	10	Dormer flashing
	11	Dormer cheeks
	12	Sarking
•	13	Roof felt
	14	Trusses
	15	Collar
	16	Insulation
	17	Parapet gutter
	18	Eaves guttering
	19	Rainwater downpipe
	20	Verge boards/skews
	21	Soffit boards
	22	Partiton wall
	23	Lath / plaster
	24	Chimney breast
	25	Window pointing
	26	Window sills
	27	Rendering
	28	Brickwork / pointing
	29	Bay window projection
	30	Lintels
	31	$\ensuremath{\textbf{C}}\xspace$ avity walls / wall ties
	32	Subfloor ventilator
	33	Damp proof course
	34	Base course
	35	Foundations
	36	Solum
	37	Floor joists
	38	Floorboards
	39	Water tank
	40	Hot water tank

### 2. CONDITION

This section identifies problems and tells you about the urgency of any repairs by using one of the following 3 categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement	
Repair category:	1
Notes:	The building is affected by past structural movement. Repairs have been undertaken in the past. There are a number of new lintels. At the back wall, there are steel straps and ties. Stonework is distorted and floors slope. There is no evidence of recent movement having occurred and the likelihood of further movement now seems remote. The presence of the structural movement has been reflected in the valuation figure.

Dampness, rot and infestation	
Repair category:	
Notes:	Within the scope of inspection, no significant dampness, rot or infestation was found.

Chimney stacks	
Repair category:	
Notes:	No obvious significant defects were noted to the chimney stacks.

Roofing including roof space

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Repair category:	1
Notes:	No obvious significant defects were noted to the roof covering or to the accessible roof space area.

Rainwater fittings	3
Repair category:	2
Notes:	There is some vegetation growing below the wallhead gutter at the front of the building. This suggest some high moisture content. There is a risk of underlying defects. Rainwater goods should be checked during wet weather and thereafter repaired as required.

Main walls	
Repair category:	2
Notes:	External stonework and cement facing at the front of the building is worn and weathered.

Windows, external doors and joinery	
Repair category:	2
Notes:	The replacement timber framed windows are worn and weathered.

External decorati	ons
Repair category:	2

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Notes:	External decorations are weathered.
--------	-------------------------------------

Conservatories / porches	
Repair category:	
Notes:	There are none.

Communal areas	
Repair category:	
Notes:	As is typical in an older property of this type, some dampness was noted at basement level, leading to the rear drying green. The replacement windows are worn.

Garages and permanent outbuildings	
Repair category:	
Notes:	No obvious significant defects were noted to the bin store in relation to the use to which it is put.

Outside areas and boundaries	
Repair category:	
Notes:	No obvious significant defects were noted to the outside areas or boundaries.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Ceilings	
Repair category:	
Notes:	The ceiling in the lounge has been partially lowered and there is a plasterboard finish. The condition of the underlying fabric is not known.
	Strapped and plaster ceilings weaken with age.

Internal walls	
Repair category:	
Notes:	There is evidence of staining on the plasterwork and cornice around the window of the front bedroom. Recent repairs have been carried out to both the external and internal fabric. Plaster is drying out. It should be monitored, to ensure that the drying process completes satisfactorily. The plaster finish is uneven in other parts of the flat.

Floors including sub-floors	
Repair category:	
Notes:	As stated above, some of the floors slope in places, reflecting past structural movement.

Internal joinery and kitchen fittings	
Repair category:	
Notes:	Internal woodwork is damaged in places, reflecting general wear and tear.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Fittings in the kitchen are no longer modern.	
---	--

Chimney breasts and fireplaces	
Repair category:	
Notes:	Moisture meter tests on chimney breasts revealed no dampness.

Internal decorations	
Repair category:	
Notes:	No obvious significant defects were noted to internal decorations.

Cellars	
Repair category:	
Notes:	There are none.

Electricity	
Repair category:	
Notes:	The system should be tested by a SELECT registered contractor, to ensure it is safe and up to date.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Repair category:	1
Notes:	All gas appliances and associated pipework should tested for safety and thereafter regularly maintained by a Gas Safe registered plumber.

Water, plumbing and bathroom fittings	
Repair category:	
Notes:	No obvious significant defects were noted to the water or plumbing systems.
	No obvious significant defects were noted to fittings in the shower room.

Heating and hot water	
Repair category:	
Notes:	The system should be regularly maintained by a heating contractor.

Drainage	
Repair category:	
Notes:	No obvious significant defects were noted to the drainage system, which has not been tested.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the comments above for detailed information

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	1
Roofing including roof space	1
Rainwater fittings	2
Main walls	2
Windows, external doors and joinery	2
External decorations	2
Conservatories / porches	
Communal areas	1
Garages and permanent outbuildings	1
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	1
Internal decorations	1
Cellars	
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

### Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

### Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

### **3. ACCESSIBILITY INFORMATION**

#### **Guidance Notes on Accessibility Information**

<u>Three steps or fewer to a main entrance door of the property:</u> In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

<u>Unrestricted parking within 25 metres</u>: For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coinoperated machines.

1. Which floor(s) is the living accommodation on?	Second
2. Are there three steps or fewer to a main entrance door of the property?	[]YES [x]NO
3. Is there a lift to the main entrance door of the property?	[ ]YES [x]NO
4. Are all door openings greater than 750mm?	[x]YES [ ]NO
5. Is there a toilet on the same level as the living room and kitchen?	[x]YES [ ]NO
6. Is there a toilet on the same level as a bedroom?	[x]YES [ ]NO
7. Are all rooms on the same level with no internal steps or stairs?	[x]YES [ ]NO
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	[x]YES [ ]NO

### 4. VALUATION AND CONVEYANCER ISSUES

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated re-instatement cost for insurance purposes.

#### Matters for a solicitor or licensed conveyancer

It is assumed the flat is burdened with a fair share of the cost of common repairs to the building of which it forms a part.

Internal alterations have been carried out to form the existing layout of the flat and the valuation assumes that all relevant Local Authority Certification is available in respect of this work.

Meadowpark Street is made up and assumed to be adopted by the Local Authority.

#### Estimated re-instatement cost (£) for insurance purposes

£145,000 (One Hundred and Forty Five Thousand Pounds).

#### Valuation (£) and market comments

The market value of the property in its present condition and with vacant possession is  $\pounds 100,000$  (One Hundred Thousand Pounds).

Report author:	Hugh G Campbell
Company name:	Glasgow North - Allied Surveyors Scotland Plc
Address:	Herbert House 24 Herbert Street Glasgow G20 6NB
Signed:	Electronically Signed: 96717-16245034-6E8D
Date of report:	30/05/2017

#### PART 2.

# MORTGAGE VALUATION CERTIFICATE

Includes a market valuation of the property.



ODESURVEY HOME REPORT							
		Mort	tgage Val	uation Re	port		
Property:	2/2 Client: Mr. Harry McGinn   24 Meadowpark Street Tenure: Absolute Ownership   Glasgow Tenure: Absolute Ownership						
Date of Inspection:	26/05/2017		Reference:	GD/4608/HG	C/AMcG		
This report has been prepared in response to your recent instructions to carry out a valuation report on the property referred to above. Please note that for most clients purchasing a property, the more detailed HOME CONDITION REPORT is recommended. This report and our inspection to which it refers have been carried out in accordance with the RICS Valuation Standards. Your attention is drawn to the additional comments elsewhere within the report, which set out the extent and limitations of the service provided. This report should be read in conjunction with the instruction acknowledgement. It is normal practice and a requirement of the RICS Valuation Standards regulations to point out that this report is for the use of the party to whom it is addressed, or their named client, or their nominated lenders, and no responsibility is accepted to any third party for the whole, or any part of its contents. Your attention is drawn to the fact that neither the whole, nor any part of this report, or any reference thereto may be included in any document, circular or statement without prior approval in writing as to the form in which it will appear							
1.0	LOCATION						
				-	ounding area is in a radius of ha		properties of
2.0	DESCRIPTIO	N		2.1 Age:	135 years		
Second floor f	lat in four storey	y tenement build	ding containing	seven flats.			
3.0	CONSTRUCT	ΓΙΟΝ					
Outer walls: g	rey sandstone,	roughcast rende	ered to rear.				
Roof: pitched and tiled.							
4.0	ACCOMMODATION						
SECOND FLOOR: Entrance hall, lounge, two bedrooms, kitchenette, shower room with wc.							
5.0	SERVICES (N	CES (No tests have been applied to any of the services)					
Water:	Mains	Electricity:	Mains	Gas:	Mains	Drainage:	Mains
Central Heati	ng:	Gas fired syst	em				
6.0	OUTBUILDIN	IGS					
Garage:		-					
Others:		Shared bin sto	ore				

7.0	<b>GENERAL CONDITION</b> - A building survey has not been carried out, nor has any inspection been made of any woodwork, services or other parts of the property which were covered, unexposed or inaccessible. The report cannot therefore confirm that such parts of the property are free from defect. Failure to rectify defects, particularly involving water penetration may result in further and more serious defects arising. Where defects exist and where remedial work is necessary, prospective purchasers are advised to seek accurate estimates and costings from appropriate Contractors or Specialists before proceeding with the purchase. Generally we will not test or report on boundary walls, fences, outbuildings, radon gas or site contamination.					
The flat appea sale.	rs to have been adequately ma	aintained having	regard to its age and characte	er. It has been p	repared for	
distorted in pla likelihood of fu	affected by structural movement aces and internally, floors slope arther movement now seems re ructural damage has been refle	. There is no ev mote. No furthe	idence of recent movement ha r structural repairs are conside	aving occurred a ered necessary.	nd the	
External stone wear and tear.	work is worn and weathered in	places. Replac	ement windows are no longer	modern and are	affected by	
8.0	ESSENTIAL REPAIR WORK	(as a condition	of any mortgage or, to preser	ve the condition	of the	
None.						
8.1 Retention	recommended:	-				
9.0	ROADS & FOOTPATHS					
Made up.						
10.0	BUILDINGS INSURANCE (£):	145,000	GROSS EXTERNAL FLOOR AREA	55 sq.metres	Square metres	
	This figure is an opinion of an appropriate sum for which the property and substantial outbuildings should be insured against total destruction on a re-instatement basis assuming reconstruction of the property in its existing design and materials. Furnishings and fittings have not been included. No allowance has been included for inflation during the insurance period or during re-construction and no allowance has been made for VAT, other than on professional fees. Further discussions with your insurers is advised.					
11.0	GENERAL REMARKS					
It is assumed	the flat is burdened with a fair s	hare of the cost	t of common repairs to the buil	ding of which it	forms a part.	
	tions have been carried out to f Authority Certification is availa			ation assumes t	hat all	
<b>12.0 VALUATION</b> On the assumption of vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, title restrictions or servitude rights. It is assumed that all necessary Local Authority consents, which may have been required, have been sought and obtained. No investigation of any contamination on, under or within the property has been made as we consider such matters to be outwith the scope of this report. All property built prior to the year 2000 may contain asbestos in one or more of its components or fittings. It is impossible to identify without a test. It is beyond the scope of this inspection to test for asbestos and future occupants should be advised that if they have any concerns then they should ask for a specialist to undertake appropriate tests.						
12.1	Market Value in present condition (£):	£100,000	One Hundred Thousand Pou	Inds		
12.2	Market Value on completion of essential works (£):					
12.3	Suitable security for normal mortgage	Yes				

	purposes?						
12.4	Date of Valuation:		26/05/2017	26/05/2017			
Signature: Electronically		Signed: 96717-	16245034-6E8D				
Surveyor: Hugh G Camp		obell		Date:	30/05/2017		
Glasgow	Glasgow North - Allied Surveyors Scotland Plc						
Office: Herbert House 24 Herbert Street Glasgow G20 6NB			Tel: 0141 337 1133 Fax: 0141 337 3007 email: glasgow.north@allie	edsurveyorssc	otland.com		



# ENERGY **Report**

A report on the energy efficiency of the property.



# energy report

### energy report on:

Property address	2/2 24 Meadowpark Street Glasgow G31 2RX
------------------	---

Customer	Mr. Harry McGinn
----------	------------------

Customer address 2/2 24 Meadowpark Street Glasgow G31 2RX	
--	--

Prepared by	Hugh G Campbell Glasgow North - Allied Surveyors Scotland Plc
-------------	--

### **Energy Performance Certificate (EPC)**

# Scotland

Dwellings

#### FLAT 2/2, 24 MEADOWPARK STREET, GLASGOW, G31 2RX

Dwelling type:	Mid-floor flat
Date of assessment:	06 September 2016
Date of certificate:	06 September 2016
Total floor area:	46 m <sup>2</sup>
Primary Energy Indicator:	221 kWh/m <sup>2</sup> /year

**Reference number:** Type of assessment: Approved Organisation: Main heating and fuel:


3116-9721-6000-0246-1902 RdSAP, existing dwelling Elmhurst Boiler and radiators, mains gas

#### You can use this document to:


- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO<sub>2</sub> emissions by improving your home

Estimated energy costs for your home for 3 years*	£1,413	See your recommendations
Over 3 years you could save*	£372	report for more information

 $^{st}$  based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions



Very environmentally friendly - lower CO<sub>2</sub> emissions



#### **Energy Efficiency Rating**

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is band C (73). The average rating for EPCs in Scotland is band D (61).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

#### Environmental Impact (CO<sub>2</sub>) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide  $(CO_2)$ emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band C (74)**. The average rating for EPCs in Scotland is band D (59).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

#### Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years	Available with Green Deal
1 Internal or external wall insulation	£4,000 - £14,000	£318.00	$\bigotimes$
2 Low energy lighting	£15	£51.00	

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.



The Green Deal may allow you to make your home warmer and cheaper to run at no up-front capital cost. See your recommendations report for more details.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE **DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE** 

# FLAT 2/2 , 24 MEADOWPARK STREET, GLASGOW, G31 2RX 06 September 2016 RRN: 3116-9721-6000-0246-1902

#### Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Sandstone or limestone, as built, no insulation (assumed)	★★☆☆☆	★★☆☆☆
	Solid brick, as built, no insulation (assumed)	★★☆☆☆	$\star \star \overleftrightarrow \Leftrightarrow \bigstar$
Roof	(another dwelling above)	—	
Floor	(another dwelling below)	—	_
Windows	Fully double glazed	★★★☆☆	★★★☆☆
Main heating	Boiler and radiators, mains gas	★★★★☆	★★★★☆
Main heating controls	Programmer, TRVs and bypass	★★★☆☆	★★★☆☆
Secondary heating	None	—	
Hot water	From main system	★★★☆	<b>★★★</b> ☆
Lighting	Low energy lighting in 40% of fixed outlets	★★★☆☆	★★★☆☆

#### The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO<sub>2</sub> emissions, running costs and the savings possible from making improvements.

#### The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 39 kg  $CO_2/m^2/yr$ .

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 1.8 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 0.6 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

Estimated energy costs for this home				
	Current energy costs	Potential energy costs	Potential future savings	
Heating	£999 over 3 years	£684 over 3 years		
Hot water	£255 over 3 years	£258 over 3 years	You could	
Lighting	£159 over 3 years	£99 over 3 years	save £372	
Totals	£1,413	£1,041	over 3 years	

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

#### **Recommendations for improvement**

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Recommended measures		Indiactive cost	Typical saving	Rating after improvement		Green	
Re	commended measures	Indicative cost per year		Energy	Environment	Deal	
1	Internal or external wall insulation	£4,000 - £14,000	£106	C 78	B 82		
2	Low energy lighting for all fixed outlets	£15	£17	C 79	B 83		

Measures which have a green deal tick  $\bigcirc$  are likely to be eligible for Green Deal finance plans based on indicative costs. Subsidy also may be available for some measures, such as solid wall insulation. Additional support may also be available for certain households in receipt of means tested benefits. Measures which have an orange tick  $\bigcirc$  may need additional finance. To find out how you could use Green Deal finance to improve your property, visit www.greenerscotland.org or contact the Home Energy Scotland hotline on 0808 808 2282.

#### Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.



#### About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

#### 1 Internal or external wall insulation

Internal or external wall insulation involves adding a layer of insulation to either the inside or the outside surface of the external walls, which reduces heat loss and lowers fuel bills. As it is more expensive than cavity wall insulation it is only recommended for walls without a cavity, or where for technical reasons a cavity cannot be filled. Internal insulation, known as dry-lining, is where a layer of insulation is fixed to the inside surface of external walls; this type of insulation is best applied when rooms require redecorating. External solid wall insulation is the application of an insulant and a weather-protective finish to the outside of the wall. This may improve the look of the home, particularly where existing brickwork or rendering is poor, and will provide longlasting weather protection. Further information can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk). It should be noted that planning permission might be required and that building regulations apply to this work so it is best to check with your local authority whether a building warrant or planning permission will be required.

#### 2 Low energy lighting

Replacement of traditional light bulbs with energy saving recommended ones will reduce lighting costs over the lifetime of the bulb, and they last up to 12 times longer than ordinary light bulbs. Also consider selecting low energy light fittings when redecorating; contact the Lighting Association for your nearest stockist of Domestic Energy Efficient Lighting Scheme fittings.

#### Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

#### Your home's heat demand

You could receive Renewable Heat Incentive (RHI) payments and help reduce carbon emissions by replacing your existing heating system with one that generates renewable heat and, where appropriate, having your loft insulated and cavity walls filled. The estimated energy required for space and water heating will form the basis of the payments. For more information go to www.energysavingtrust.org.uk/scotland/rhi.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	4,038	N/A	N/A	(2,067)
Water heating (kWh per year)	1,630			

#### Addendum

This dwelling has stone walls and so requires further investigation to establish whether these walls are of cavity construction and to determine which type of wall insulation is best suited.

## FLAT 2/2 , 24 MEADOWPARK STREET, GLASGOW, G31 2RX 06 September 2016 RRN: 3116-9721-6000-0246-1902

#### About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Assessor membership number: Company name/trading name:	Mr. Hugh Campbell EES/016940 Allied Surveyors Scotland Plc
Address:	24 Herbert Street
	Glasgow G20 6NB
Phone number:	0141 337 1133
Email address: Related party disclosure:	Hugh.campbell@alliedsurveyorsscotland.com No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

#### Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

#### Opportunity to benefit from a Green Deal on this property

Under a Green Deal, the cost of the improvements is repaid over time via a credit agreement. Repayments are made through a charge added to the electricity bill for the property.

To see which improvements are recommended for this property, please turn to page 3. You can choose which improvements you want to install and ask for a quote from an authorised Green Deal provider. They will organise installation by an authorised Green Deal installer. If you move home, the responsibility for paying the Green Deal charge under the credit agreement passes to the new electricity bill payer.

For householders in receipt of income-related benefits, additional help may be available.

To find out more, visit www.greenerscotland.org or call 0808 808 2282.



#### PART 4.

# PROPERTY QUESTIONNAIRE

The owner of the property is required to complete this document which asks for information on the property such as 'Which council tax band?' etc.



# **Property Questionnaire**

**Property Address** 

2/2 24 Meadowpark Street Glasgow G31 2RX

Seller(s)

Harry McGinn

Completion date of property questionnaire

Note for sellers

1.	Length of ownership		
	How long have you owned the property? July 2007		
2.	Council tax		
	Which Council Tax band is your property in? (Please circle) []A []B []C [x]D []E []F []G []H		
3.	Parking		
	What are the arrangements for parking at your property? (Please tick all that apply)		
	Garage	[]	
	Allocated parking space	[]	
	Driveway	[]	
	Shared parking	[]	
	On street	[x]	
	Resident permit	[]	
	Metered parking	[]	
	Other (please specify):		

# property questionnaire

4.	Conservation area		
	Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?	[ ]YES [x]NO [ ]Don't know	
5.	Listed buildings		
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	[]YES [x]NO	
6.	Alterations/additions/extensions		
а	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	[ ]YES [x]NO	
	If you have answered yes, please describe below the changes which you have made:		
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	[ ]YES [ ]NO	
	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.		
	If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:		
b	Have you had replacement windows, doors, patio doors or double glazing installed in your property	[]YES [x]NO	
	If you have answered yes, please answer the three questions below:		
	(i) Were the replacements the same shape and type as the ones you replaced?	[ ]YES [ ]NO	
	(ii) Did this work involve any changes to the window or door openings?	[ ]YES [ ]NO	
	(iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed):		
	Please give any guarantees which you received for this work to your solicitor or estate agent.		

7.	Central heating		
а	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property - the main living room, the bedroom(s), the hall and the bathroom).	[x]YES [ ]NO [ ]Partial	
	If you have answered yes or partial - what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air). <i>Gas fired</i>		
	If you have answered yes, please answer the three questions below:		
	(i) When was your central heating system or partial central heating system installed? <i>Pre 2007</i>		
	(ii) Do you have a maintenance contract for the central heating system?	[]YES [x]NO	
	If you have answered yes, please give details of the company with which you have a maintenance contract		
	<ul><li>(iii) When was your maintenance agreement last renewed?</li><li>(Please provide the month and year).</li></ul>		
8.	Energy Performance Certificate		
	Does your property have an Energy Performance Certificate which is less than 10 years old?	[x]YES [ ]NO	
9.	Issues that may have affected your property		
а	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	[x]YES [ ]NO	
	If you have answered yes, is the damage the subject of any outstanding insurance claim?	[]YES [x]NO	
b	Are you aware of the existence of asbestos in your property?	[]YES [x]NO	
	If you have answered yes, please give details:		
10.	Services		
а	Please tick which services are connected to your property and give details of the supplier:		

	Services	Connected	Supplier
	Gas or liquid petroleum gas	Y	Scottish Power
	Water mains or private water supply	Y	
	Electricity	Y	Scottish Power
	Mains drainage	Y	
	Telephone	Ν	
	Cable TV or satellite	Ν	
	Broadband	Ν	
b	Is there a septic tank system at your property	y?	[]YES [x]NO
	If you have answered yes, please answer the two questions below:		
	(i) Do you have appropriate consents for the discharge from your septic tank?		[ ]YES [ ]NO [ ]Don't know
	(ii) Do you have a maintenance contract for your septic tank?		[ ]YES [ ]NO
	If you have answered yes, please give details of the company with which you have a maintenance contract:		
11.	Responsibilities for shared or common areas		
а	Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area? If you have answered yes, please give details:		[ ]YES [x]NO [ ]Don't know
b	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas? If you have answered yes, please give details:		:e [x]YES [ ]NO [ ]N/A
	Property is factored.		
с	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?		f [ ]YES [x]NO
d	Do you have the right to walk over any of your neighbours' property- for example to put out your rubbish bin or to maintain your boundaries? If you have answered yes, please give details:		n [ ]YES [x]NO
е	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their		[ ]YES [x]NO

	rubbish bin or to maintain their boundaries? If you have answered yes, please give details:	
f	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privatelyowned.) If you have answered yes, please give details:	[ ]YES [x]NO
12.	Charges associated with your property	
а	Is there a factor or property manager for your property? If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:	[x]YES [ ]NO
	<i>Newton Property Management 87 Port Dundas Road Glasgow G4 0HF 0141 3539706 approximately £60-£65 per quarter</i>	
b	Is there a common buildings insurance policy?	[ ]YES [x]NO [ ]Don't know
	If you have answered yes, is the cost of the insurance included in your monthly/annual factors charges?	
с	Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.	
	None	
13.	Specialist works	
а	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?	[]YES [x]NO
	If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.	
b	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?	[]YES [x]NO
	If you have answered yes, please give details:	
с	If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?	[ ]YES [ ]NO
	If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or	

estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may	
be shown in the original estimate. Guarantees are held by:	

14.	Guarantees		
а	Are there any guarantees or warranties for any of the following:		
(i)	Electrical work	[x]NO [ ]YES [ ]Don't know [ ]With title deeds [ ]Lost	
(ii)	Roofing	[x]NO [ ]YES [ ]Don't know [ ]With title deeds [ ]Lost	
(iii)	Central heating	[x]NO [ ]YES [ ]Don't know [ ]With title deeds [ ]Lost	
(iv)	) National House Building Council(NHBC) [X]NO []YES []Don't know []With title deeds []L		
(v)	Damp course [x]NO [ ]YES [ ]Don't know [ ]With title deeds [ ]Los		
(vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy) [X]NO []YES []Don't know []With title deeds		
b	If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s):		
с	Are there any   outstanding claims     outstanding claims   []YES [x]NO     guarantees listed   above?		
	If you have answered yes, please give details:		

15.	Boundaries		
	So far as you are aware, has any boundary of your property []YES [x]NO []Don't know		
	If you have answered yes, please give details:		
16.	Notices that affect your property		
In the past three years have you ever received a notice:			

а	advising that the owner of a neighbouring property has made a planning application?	[ ]YES [x]NO
b that affects your property in some other way?		[]YES [x]NO
с	that requires you to do any maintenance, repairs or improvements to your property?	[]YES [x]NO
	If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property.	

# Declaration by the seller(s)/or other authorised body or person(s) I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s):	Harry McGinn
Capacity:	[x]Owner [ ]Legally Appointed Agent for Owner
Date:	06/09/2016